

MELBOURN PARISH COUNCIL

District of South Cambridgeshire

Meeting: 22 October 2020 (Maintenance Committee)

Agenda Item: MA057 20a)

Date of Report: 15 October 2020 : Clear Crescent play equipment

Thank you for returning the drawings identifying the affected timber on your Cableway. This information has been passed on to our sister company Fawns.

With regard to your query

'As the upright on the opposite side is made of the same material and therefore also likely to deteriorate, would Wicksteed consider replacing this at the same time'.

The only time this would be an issue is if the timber showed signs of rot. All timbers should be checked as part of your ongoing inspection and maintenance regime and if any signs of rot are apparent this should be picked up at that time.

If I can be of any further help please do not hesitate to contact me.

Kind Regards,

Cheryl

From: Parish Clerk [<mailto:parishclerk@melbournpc.co.uk>]

Sent: 02 October 2020 11:21

To: Cheryl Graham <installationsadmin@wicksteed.co.uk>

Subject: RE: FAO Claire Littlewood - Case Acknowledgement 110-11717

Good morning Cheryl

Thanks for your email. I have marked on the attached drawing the upright that requires replacement (highlighted orange). As the upright on the opposite side is made of the same material and therefore also likely to deteriorate, would Wicksteed consider replacing this at the same time.

Many thanks
Claire

Claire Littlewood
Parish Clerk

From: Cheryl Graham <installationsadmin@wicksteed.co.uk>

Sent: 30 September 2020 10:14

To: Assistant Clerk <assistantclerk@melbournpc.co.uk>

Subject: FAO Claire Littlewood - Case Acknowledgement 110-11717

Dear Claire.

I am sorry to hear that you have a problem at Clear Crescent Park with your Cableway. Please be advised that this has been registered on our system under case number 110-11717. Details have been forwarded to our sister company, Fawns, who will review the information provided.

In order for us to identify the correct timber for your Cableway, could I please ask that you mark/circle on the attached drawing the affected timber and return this to me.

If not already done so, we would recommend that you remove the seat and chain until such time that the rotten timbers have been replaced.

Kind regards