

Clear Crescent – remedial works from Rospa report

- 1) Agility Trail – The report identified that the top bar is rotting.

Good Morning Sophie

Many thanks for your email and I apologise about the delay in coming back to you. Jodie has passed the enquiry re the agility trail onto the office and is dealing with the surfacing enquiry herself. Please find below quotation for a cost to supply the parts required and also for an engineer to fit the parts.

CODE	DESCRIPTION	UNIT	QTY	TOTAL
	TO SUPPLY AND FIT THE FOLLOWING COMPONENT PARTS TO THE EXISTING DROP ROPE TRAVERSE AT CLEAR CRESCENT PLAY AREA, MELBOURN, SG8 6JD			
FS610-SPEC	Drop rope traverse top beam – full dimensions required	£ 194.35	1	£ 194.35
Carriage	Carriage from supplier (Fawns)	£ 175.00	1	£ 175.00
L-Maintenance	Labour cost to fit the above	£360.00	1	£360.00
	TOTAL EX VAT			££729.35

Lead time of the part is approx. 16 weeks from receipt of order - fitting of these parts will follow 2weeks from when the part is available.

Please note this is not an official quotation.

Errors and Omissions Excluded.

If I can be of any further assistance please do not hesitate to contact me.

- 2) Embankment slide – The report identified that the area underneath the slide needs resurfacing

Morning Sophie,

I'm so sorry about this but I'm having trouble getting any quick answers.

The approximate cost to build up the area all the way around the embankment slide and re-surface with EcoTumble would **be £4,985.00 + VAT**, however, I am still waiting for our contracts manager coming back to me to confirm this is correct.

Many Thanks