Doc. No.: 4.23 Version: <u>65</u> Date approved: 27 July 2022June Review date: <u>JuneMay</u> 2025

POLICY AND PROCEDURE: Parish Estate - Safety Inspections

PURPOSE: To ensure public spaces for which the Melbourn Parish Council (hereafter the Council) has responsibility, are routinely inspected and maintained such that users are offered safe access

SCOPE: All public spaces in the Melbourn Parish Estate for which the Council has direct accountability. Aspects of the public environment that are the responsibility of other agencies, for example public highways or school grounds, are not covered by the scope of this policy.

Note: Appendix 1 lists those areas deemed in need of regular safety inspection, together with Risk Assessments defining the required frequency of inspection for each. Not all areas have similar risks, and inspection frequency varies accordingly.

1. POLICY:

- 1.1 It is the policy of the Council that all areas listed in Appendix 1 of this document are regularly inspected for hazards.
- 1.2 Because different areas present different levels of risk, not all areas will be inspected at the same frequency.
- 1.3 In order to decide the inspection frequency a formal Risk Assessment will be carried out for each affected area as listed in Appendix 1.
- 1.4 Risk levels will be divided into 'High', 'Medium' and 'Low'. High Risk areas will be inspected weekly. Medium Risk areas will be inspected every two weeks. Low Risk areas will be inspected monthly. More frequent inspections can be carried out, depending on circumstances, for example an unusual spillage or a village public event.
- 1.5 Risk Score Bands: 0 11 Monthly; 12 19 Two Weekly; 20 + Weekly
- 1.6 It is the responsibility of the Clerk to the Council to administer the safety checking system through the Village Wardens.
- 1.7 It is the responsibility of the Village Wardens to ensure that proper inspection checks are carried out on all listed areas, according to the frequencies laid out in this document.
- 1.8 Where agreed, nominated Councillors may carry out area checks, provided such checks are properly and formally recorded.

Doc. No.: 4.23 Version: <u>65</u> Date approved: 27 July 2022 June Review date: <u>JuneMay</u> 2025

2. PROCEDURE:

- 2.1 Village Wardens will agree each week those areas that will be inspected and by whom.
- 2.2 Inspections will be shared to make the work sensibly balanced. The timing of inspections can be varied during the working week to make the visiting of remote areas time-efficient.
- 2.3 Inspections will be recorded on the Inspection Record Sheet; this is included as Appendix 3 to this document.
- 2.4 Each inspection will be signed and dated. Any issues or actions required must be noted.
- 2.5 It is the objective to leave each area in a safe condition after inspection. Should this not be possible, due to some significant problem, the matter should be notified to the Clerk so that steps can be quickly taken to correct the deficiencies.
- 2.6 Completed monthly inspection sheets must be returned to the Clerk for retention

Document Approval:

(Chair to Melbourn Parish Council)

Date of Parish Council meeting: 25 July 2022 13 June 2024

Review Policy: Every 12 months

Doc. No.: 4.23 Version: 65 Date approved: June 202427 July Review date: May 2025

APPENDIX 1

		Risk	Factors (Sc	ore 1 low –	5 high)		Total Score	Risk Level High/Medium/Low
Area	Young Children Use	Youth Attention and Use	Traffic Hazards	Sports Use	Level of Footfall	Elderly Persons Use		
Moor Play Park	5	5	0	1	5	5	21	High
All Saints Churchyard	0	5	0	0	3	5	13	Medium
Orchard Road Cemetery	1	2	0	0	5	5	13	High (due to bin emptying needs)
Old Recreation Ground	2	4	0	5	4	3	18	Medium
New recreation Ground	2	3	0	5	5	3	18	Medium
Village Car Park	5	5	5	0	5	5	25	High
War Memorial	4	5	2	0	5	5	21	High
Littlehands and Access Way	5	5	4	2	5	3	24	High
Melbourn Hub and Gardens	5	5	0	0	5	5	20	High
Stockbridge Meadows	3	5	0	0	3	4	15	Medium

Doc. No.: 4.23 Version: 65 Date approved: June 202427 July Review date: May 2025

		Risk						
Area	Young Children Use	Youth Attention and Use	Traffic Hazards	Sports Use	Level of Footfall	Elderly Persons Use	Total Score	Risk Level High/Medium/Low
Fire Engine Shed	0	2	3	0	1	1	7	Low
Jubilee Orchard	3	3	0	1	3	3	12	Medium
Clear Cres.Play Park	5	5	0	1	5	5	21	High
Armingford Cres.	2	2	2	2	1	1	10	Low
Worcester Way	3	3	1	2	2	1	12	Medium
Beechwood Avenue	2	3	0	2	3	1	11	Low
Chalkhill Barrow	2	2	2	1	2	1	10	Low
Elm Way	2	2	2	1	2	1	10	Low
Millenium Copse	2	5	0	0	3	1	11	Low
BMX Site	4	5	0	5	3	0	17	Medium
Allotments	1	4	0	0	4	4	13	Medium
New Road Cemetery	3	3	1	3	5	5	20	High

Doc. No.: 4.23 Version: 5

Date approved: 27 July 2022 Review date: July 2023

APPENDIX 3

	NOTES			
Week 1	Week 2	Week 3	Week4	
				4-
	Week 1		Week 1 Week 2 Week 3	

Formatted Table

Doc. No.: 4.23 Version: 5

Date approved: 27 July 2022 Review date: July 2023

<u>Pavilion</u> <u>Defibrillator</u>			
Doctors Surgery Defibrillator			
Beechwood Avenue			
Millennium Copse			
Worcester Way			
Allotments			
Fire Engine Shed			
Chalkhill Barrow			
Elm Way			
Stockbridge M.			

Doc. No.: 4.23 Version: 5

Date approved: 27 July 2022 Review date: July 2023

Pavilion : Legionella monitoring	Responsibility	Weekly (please note date completed)	Monthly (note insert date completed)	Quarterly (note insert date completed)	Annually (note insert date completed)
Record flushing of infrequently used outlets ** (run showers and taps, flush toilets – to be done weekly) – log when done	Wardens				
Formal thermal control and hygiene regime – MPC to provide appropriate thermometer	Wardens				
Record cleaning and descaling	Cleaning contractor				
Showers – descale and disinfect	Cleaning Contractor				
Disinfect hot water unit in kitchen	Cleaning Contractor				
Hot water cylinders – check water temp (should be 60c)	Wardens				
Fit automatic flushing values to expansion vessels OR flush regularly (to be carried out in conjunction with above **)	Wardens				
Service all TMVs annually – to be done as part of annual service of heating system	Heating contractor				
Check insulation to pipework where required	Heating contractor				

Doc. No.: 4.23 Version: 5 Date approved: 27 July 2022 Review date: July 2023

HOT AND COLD-WATER SERVICES - RECOMMENDED TESTING & MAINTENANCE PROGRAMME

SERVICE	TASK	FREQUENCY
HOT WATER SERVICE	Arrange for samples to be taken from hot water calorifiers, in order to note conditions of drain water.	ANNUALLY
	Visual check on internal surfaces of calorifiers for scale or sludge. Check representative taps for temperatures as above on a rotational basis.	ANNUALLY
	Check temperatures in flow and return at calonfiers.	MONTHLY
	Check water temperatures up to one minute to see if it has reached 50°C at the sentinel taps. (55°C Healthcare)	MONTHLY
COLD WATER SERVICE	Visually inspect cold water storage tanks and carry out remedial work where necessary. Check representative taps for temperature as above on a rotational basis.	ANNUALLY
	Check tank water temperatures remote from ball valve and mains temperature at ball valve. Note maximum temperatures recorded by fixed max/min thermometers where fitted.	BI-ANNUAL
	Check that temperature is below 20°C after running the water for up to 2 minutes in sentinel taps.	MONTHTLY
SHOWER HEADS	Dismantle, clean and descale shower heads and hoses.	AS NECCESARY
LITTLE-USED OUTLETS	Flush through and purge to drain, or purge to drain immediately before use, without release of aerosols.	WEEKLY

Doc. No.: 4.23 Version: 5 Date approved: 27 July 2022 Review date: July 2023

HOT AND COLD-WATER SERVICES - TEMPERATURE CONTROL REGIME

FREQUENCY	СНЕСК	ACQUIRED	STANDARD	NOTES	
		COLD	нот		
MONTHLY	Sentinel Taps	The water temperature should be below 20°C after running the water for up to two minutes.	The water temperature should be at least 50°C within a minute of running the water. (55°C Healthcare)	This check makes sure that the supply and return temperatures on each loop are unchanged, i.e. the loop is functioning as required.	
	If fitted, input to TMV's on sentinel basis.		The water supply to the TMV temperature should be at least 50°C within a minute of running the water. (55°C Healthcare)	One way of measuring this is to use a surface temperature probe.	
	Water leaving and returning to water heater/calorifier.		Outgoing water should be at least 60°C and the return at least 50°C.	If fitted, the thermometer pockets at the top of the water heater/calorifiers and the return leg are useful points for accurate temperature measurements. If installed, these measurements could be carried out and logged by a building management system.	
BI-ANNUAL	Incoming cold-water inlet (at least once in the winter and once in the summer).	The water should preferably be below 20°C at all times.		The most convenient place to measure is usually at the ball valve inlet to the coldwater storage vessel.	
ANNUALLY	Representative number of taps on a rotational basis.	The water temperature should be below 20°C after running the water for two minutes.	The water temperature should be at least 50°C within a minute of running the water. (55°C Healthcare)	This check makes sure that the whole system is reaching satisfactory temperatures for Legionella control.	

Doc. No.: 4.23 Version: 5 Date approved: 27 July 2022 Review date: July 2023

SUBJECTS REVIEWED	YES/NO	COMMENTS	DATE ACTIONED
RISK ASSESSMENT			REVIEWED
Are the current system details correct?	New risk assessment	Available within this Assessment	18/02/2021
Is there a current up to date cold water cistem/tank survey?	No water tanks found	Available within this Assessment	
Is there a current photograph of the cistem/tank(s)?	n/a	Available within this Assessment	
Is there a current up to date hot water survey?	YES	Available within this Assessment	
Is there a current photograph of the calorifier/water heater(s)?	YES	Available within this Assessment	
Are the schematic drawing details correct?	YES	Available within this Assessment	
Does the assessment need up dating?	NO	Available within this Assessment	
LOG BOOK			\$=====================================
Is the maintenance schedule up to date?	NO		
Are the Responsible Person details up to date?	YES	**	
Is the training log up to date?	NO	9	
Have any training requirements been identified?	YES		
Is there an annual review of the system?	YES		
Are the disinfection procedures being followed?	NO		
Are all the log sheet entries up to date?	NO	3	
Has any remedial works been identified and recorded?	YES		
Has identified remedial work been rectified?	NO	2	2
Are outlets cleaned/disinfected on a minimum of annually and certified?	NO	(C)	
Has the system been tested for legionella and oertified?	YES	2	
Has the annual mains water analysis been recorded and certified?	NO		
SUMMARY OF COMPLIANCE WITH ACOP		0 0	
Has the system been adequately risk assessed?	YES	Available within this Assessment	
Is the scheme satisfactory for minimising the risk?	No scheme in place		
Has the scheme been fully implemented?	NO	3	P.
Are the records being kept up to date by all responsible/competent personal?	NO	S 2	
Does the scheme effectively function in line with the requirements of the ACOP (L8)?	NO		

Client is to fill in actioned section to conform to current legislation.

Doc. No.: 4.23

Version: 5

Date approved: 27 July 2022 Review date: July 2023