

Formatted Table

Asbestos Management Plan : St Georges and Grays Allotments

Purpose: To set out the management plan for reducing the risk of exposure to asbestos on the allotments and to set out the procedure for removing asbestos when it is found.

Section 1 – Overview:

Asbestos was widely used by the construction industry before 1995. Products such as cement sheets, roof panels, ceiling tiles, ceiling coatings and PVC floor tiles may all contain asbestos. Not all asbestos material presents the same risk.

The type of asbestos that is generally found on the allotment sites is white asbestos in the form of cement panels and usually found as fragments in the soil. The white asbestos is generally considered "low risk" because the asbestos fibres are bonded with the material so it is more difficult for them to be released into the air. Asbestos is not considered hazardous as long as it remains in place and undamaged. It is only when materials containing asbestos are damaged that there is potential for asbestos fibres to be released into the air and inhaled.

St George's allotments historically had buildings on the site that are believed to have been constructed using asbestos cement. Due to the history of the allotment site, the Parish Council treats all materials suspected of containing asbestos as asbestos and will follow the protocol in section 4.

Section 2 - Responsibility:

As the land owner, the Parish Council is responsible for implementing the Asbestos Management Plan and the Allotment Association will help to facilitate the plan.

All plot holders are responsible for acting in accordance with the plan and reporting issues to the Allotment Association and Parish Council.

The contact details for the Parish Council and Allotment Association can be found below. When reporting asbestos, you must inform both organisations.

Name	Contact Details	Organisation
Sophie Marriage Alex Coxall	assistantclerk@melbournpe.co.uk parishcouncil.gov.uk 01763 3263303 (option 3)	Melbourn Parish Council
Graham Place (secretary) Chris Selway (chairman)	Gaplace10@gmail.com; gardenrobot@AOL.com	Allotment Association

Formatted Table

Formatted: Indent: Left: 0 cm

Section 3 - General safety advice:

Asbestos is only dangerous when it is disturbed and when managed safely and contained it does not present a hazard. If you do come across a piece of material that you suspect may contain asbestos, do not break or damage it to avoid release of hazardous fibres.

It should be noted that plants can only absorb water soluble minerals and asbestos is not water soluble, so it is safe to plant, grow, and consume produce from the allotments. It is advisable to wash produce with clean water before use. As always, children should be supervised at all times when they are on the allotments.

An Asbestos Survey Report was carried out on 2nd November 2022 to identify, as far as reasonably practicable, the presence and extent of any suspect asbestos containing materials (ACMs) and to assess

the risks during activities on the site. The materials found at the allotments were deemed "low" risk overall risk for the site was categorized as "very low".

ACMs within this category are predominantly not readily accessible, unlikely to be disturbed and due to their nature, condition, location or extent, and would lead to minimal fibre release if they were disturbed. The survey advises that visual inspections should be made on an annual basis to ascertain any change in condition and where such a change occurs, should be appropriately assessed, scored and re-prioritised. It has been recommended that any identified ACMs (bounded) are removed under partially controlled conditions by fully licensed contractors.

If you are unsure about whether a piece of material contains asbestos, you should presume it does and follow the steps set out in section 4.

Section 4 –What to do when material that may contain asbestos is found on a plot:

The steps in sections 4 have been guided by the findings and recommendations from the Asbestos Survey Report 2022 and information from the Health and Safety Executive.

Step 1: Holder identifies piece(s) of material that may contain asbestos on allotment plot

Step 2: Holder takes care not to disturb the material that may contain asbestos, by leaving the material where it is or by wetting the material thoroughly with water, then moving it with a trowel/spade to a more suitable area on their plot. The holder must mark the location of the material with a red marker. Red markers are kept in the box next to the noticeboard at the entrance to the site

Step 3: Holder informs Parish Office and Allotment Association (via contact details in Section 2) that they have identified material that may contain asbestos and have marked exact location of the material.

Step 4: The Parish Office will arrange clearance annually. It will be up to the discretion of the Clerk/Maintenance committee if more frequent clearances are required. The holder will not disturb the area where the material that may contain asbestos has been identified until the Parish Office confirms that clearance is complete.

Step 5: The Parish Office confirms clearance of the material and the holder can resume gardening in this area.

Section 5 – Long term plan to reduce the risk of exposure to asbestos:

Pieces of asbestos have been found across the allotments over several years. In order to reduce the amount of asbestos and in accordance with the recommendations from the Asbestos Survey Report, the Parish Council will arrange for a licensed contractor to carry out yearly site inspections in the spring time, to monitor the presence and extent of asbestos and to clear any visible asbestos. This will reduce the amount of asbestos at the allotments over time. The introduction of yearly site inspections will be reviewed annually to monitor its effectiveness.



Document Approval:

(Chair to Melbourn Parish Council)

Date of Parish Council Meeting: ~~16 January 2023~~24 February 2025

Document Review Policy: 2 years from last approval

Formatted Table