

Good Afternoon,

We carried out all works on quote 27783, this will therefore be charged out fully. I will chase this invoice up for you.

The doors just weren't left working as the sensors cant link to the operators as they are too old as you said below.

We then quoted 28247 to replace the operators on the doors where we have already fitted new sensors so that the doors will work properly.

28247 is to replace both operators. The actual doors are not being replaced.

Yes a quote will follow asap from the works carried out last week.

Hope that's all okay 😊